

# Decal Application Instructions

1. Clean the application surface with an adhesive cleaner (found at most automotive stores) or lacquer thinner and let dry completely.
2. Use a wetting solution; we suggest soapy dish water, but Windex window cleaner will work in a pinch. Spray area where decal will be placed.
3. Start one edge of the decal and work to the opposite edge using just enough pressure to secure decal. Be careful not to allow decal to touch any area not treated with a wetting solution; it is very difficult to remove decal from untreated areas.
4. Dry the entire area with a clean cloth and re-squeegee. Ultimate adhesion will occur in 24 to 48 hours.

**Tip: After applying all decals use a hair dryer for better adhesion.**

